





x1




x1



x1



x1









x0 → 4

ø4x16 mm







x4








1





Unidades en milímetros | Units in millimeters | Unités en millimètres

2




Unidades en milímetros | Units in millimeters | Unités en millimètres


3




4




5










6



7





* Tornillos recomendados | Recommended screws | Vis recommandées

